



**NISSAN NV200: 1LDP844**

Vinnnumber:	<b>VSKHBAM20U0113101</b>	Versionname:	<b>1.5 DCI 66KW BUSINESS SSD</b>
First Registrationdate:	<b>28/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>82975</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3632</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>175/70/14/93 T Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	288,06
-------------------	--------

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Tailgate, Deformed / Strained, Acceptable	0,00
---	------



Wing R R, Repaired, Acceptable	0,00
--------------------------------	------

*No pictures to display*

Sliding door R, Repaired, Acceptable	0,00
--------------------------------------	------

*No pictures to display*

Trunk door R L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Sidewall RL (LCV), Dent(s), It - Spot repair 115,56



Wheel cover F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Ignition key, Missing, E - Replace 150,00

*No pictures to display*

Bonnet, Dent(s), Acceptable 0,00

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace 22,50



Bodywork, Not original part, Acceptable 0,00

*No pictures to display*