


AUDI A1 SPORTBACK: 1PZK888			
Vinnumber:	WAUZZZ8X5HB034175	Versionname:	1.4 TDI 66kW
First Registrationdate:	19/10/2016	Fiscalpower:	
Expertise Mileage:	83398	Power Kw:	66
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3113
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Luggage cover
GPS storage	SD Rear parking sensors
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	185/60/15/84 H LightMetal			
	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	228,24
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Windscreen repair	58,80



Wing R R, Dent(s) and scratch(es), Acceptable	0,00
-----------------------------------------------	------



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

