



LU Mercedes s: KB7077

Vinnnumber:	WDD2221851A293114	Versionname:	S 500 4MATIC longue
First Registrationdate:	5/10/2016	Fiscalpower:	
Expertise Mileage:	76122	Power Kw:	335
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	SERV A IN 79 DAGEN	Parking lot:	2531
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats R heated
TV/DVD screen R		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Seats R ventilated
Windows electric F		Seats F L ventilated
Windows electric R		Seats F R ventilated
Cruise Control		Sun Roof electric
Steering wheel multifunctional		Panoramic roof
Seats F heated		Central consol F
Type of headlighting	Headlighting LED	Front parking sensors
Type of GPS	GPS big screen color	Rear parking sensors
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/20/99 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT **611,12**

Alloy rim F R polished, Scratch(es), I - Repair **95,00**



Maintenance, Maintenance, P - Check **0,00**



Alloy rim R L polished, Scratch(es), I - Repair 95,00



Wing F R, Scratch(es), It - Spot repair 115,56



Alloy rim F L polished, Scratch(es), I - Repair 95,00



Bumper R, Scratch(es), It - Spot repair 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), I - Repair 95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display