


OPEL Zafira: 1HBV837

Vinnumber:	WOLPE9E3XE2088752	Versionname:	ZAFIRA TOURER
First Registrationdate:	13/06/2014	Fiscalpower:	ecoFL.Cosmo S/S 136PK
Expertise Mileage:	69455	Power Kw:	100
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1129
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			819,35
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80


Rearview mirror housing R, Scratch(es), Smart repair
110,64




Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Scratch(es), It - Spot repair 115,56



Door F R, Scratch(es), Acceptable 0,00

No pictures to display