


BMW 1 HATCH: GZ4374

| | | | |
|-----------------------------------|--------------------------|--------------|--|
| Vinnumber: | WBA1V91030V739422 | Versionname: | 1.5 116D EFFICIENTDYNAMICS EDIT. (85KW) |
| First Registrationdate: | 13/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 61153 | Power Kw: | 85 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Back | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 2214 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting LED | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |
| Sport seats | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/50/17/89 W LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 4 mm | Re.R. | Bridgestone: 4 mm |

Assistance equipment

 Runflat **Yes**

| | |
|---|----------------|
| Total cost ex VAT | 2251,55 |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 404,20 |



| | |
|---|---------------|
| Door panel F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Dent(s) and scratch(es), Le - Replace and paint | 735,00 |



| | |
|---|--------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 366,35 |



| | |
|---|--------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Dent(s) and scratch(es), Le - Replace and paint | 651,00 |



| | |
|--|-------|
| Door R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Certificate Of Conformity, Missing, P - Check | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |

