



BMW 5 TOURING: 1LJZ947

Vinnumber:	WBA5L31040G084051	Versionname:	2.0 520D (140KW) TOURING
First Registrationdate:	8/10/2015	Fiscalpower:	
Expertise Mileage:	139133	Power Kw:	140
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	-400KM	Parking lot:	1122
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1278,96
-------------------	---------

Protection plate M, Tear, E - Replace	89,00
---------------------------------------	-------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------



Maintenance, Maintenance, Execute 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 0,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 766,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wheel arch cover F R, Broken, E - Replace 74,00

