



**MERCEDES CLA: 1HHD268**

Vinnnumber:	<b>WDD1173121N114095</b>	Versionname:	<b>CLA BER 180 CDI 109PK</b>
First Registrationdate:	<b>22/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>96790</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>SERVICE A IN 12900KM</b>	Parking lot:	<b>4209</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1652,50</b>
-------------------	----------------

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper trim R, Dent(s) and scratch(es), E - Replace 91,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Crack, Le - Replace and paint 651,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Backrest cover F L, Worn, Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



