



## SEAT Alhambra: 1HJV568

Vinnnumber:	<b>VSSZZ7NZFV501234</b>	Versionname:	<b>ALHAMBRA Ecom.Style</b>
First Registrationdate:	<b>5/08/2014</b>	Fiscalpower:	<b>DPF 136PK</b>
Expertise Mileage:	<b>100762</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4611</b>
Maintenance:	<b>BINNEN 21600 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/60/16/99 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

## Assistance equipment

Repair kit	<b>No</b>	Compressor	<b>No</b>
Total cost ex VAT			<b>703,72</b>
Tyre repair kit, Missing, E - Replace			<b>252,64</b>



Bumper R, Scratch(es), Acceptable

0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Door R L, Dent(s), Acceptable 0,00



Wing F L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R, Deformed / Strained, E - Replace 277,44



Wing F L, Scratch(es), Acceptable 0,00

