



SEAT LEON ST: 1LFR281

Vinnnumber:	VSSZZZ5FZGR043754	Versionname:	1.6 TDI 81KW STYLE
First Registrationdate:	15/09/2015	Fiscalpower:	
Expertise Mileage:	169222	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3619
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Semperit: 2 mm	Fr.R.	Semperit: 2 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	561,00
-------------------	--------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Boot carpet, Missing, E - Replace	45,00
-----------------------------------	-------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	125,00



Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance, Maintenance, Execute	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tyre F R, Tear, E - Replace	132,00



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Trunk lid covering R, Scratch(es), E - Replace	109,00
--	--------

