



SKODA Octavia: 1FQQ741

Vinnumber:	TMBAG7NE0E0061191	Versionname:	OCTAVIA BER Ambition
First Registrationdate:	25/09/2013	Fiscalpower:	105PK
Expertise Mileage:	113870	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	1313
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1025,13
-------------------	----------------

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	---------------






Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	-------------

No pictures to display

Maintenance, Maintenance, Execute	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bonnet, Dent(s), PDR - Paintless dent repair	63,00
	
Door F L, Scratch(es), Acceptable	0,00
