



VOLKSWAGEN Golf: 1FRR638			
Vinnnumber:	WVWZZZAUZEP520788	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	3/10/2013	Fiscalpower:	
Expertise Mileage:	45095	Power Kw:	77
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2403
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			423,60
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80
---	--	--	--------



No pictures to display