


**SKODA Superb: 1HXX356**

Vinnnumber:	<b>TMBAJ73T3F9026175</b>	Versionname:	<b>SUPERB BER Ambition</b>
First Registrationdate:	<b>24/10/2014</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>161792</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>-9800</b>	Parking lot	<b>2622</b>
Maintenance	<b>NOT OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>HD</b>	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/94 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT	<b>1675,54</b>
-------------------	----------------

Door F L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Door F R, Dent(s), LI - Repair and paint (complete)	<b>382,02</b>
---	---------------



Maintenance, Maintenance, Execute	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Rearlight R , Broken, E - Replace	<b>132,00</b>
-----------------------------------	---------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Tyre repair kit, Missing, E - Replace 252,64



Windscreen, Stone chip(s), Windscreen repair 0,00



Door frame R R, Dent(s), It - Spot repair 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

