



BMW 3: 1EZG627

Vinnumber:	WBA3K91020F930194	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	26/04/2013	Fiscalpower:	
Expertise Mileage:	51881	Power Kw:	85
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2205
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Jack	Yes
------------	------------	------	------------

Total cost ex VAT	1666,56
-------------------	----------------

Door R L, Repaired, Acceptable	0,00
--------------------------------	-------------

<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,48
---	---------------

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,10



Door panel F L, Scratch(es), E - Replace 114,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

