



BMW 1 HATCH: HZ5849			
Vinnumber:	<b>WBA1S51090V834522</b>	Versionname:	<b>2.0 118D (110KW)</b>
First Registrationdate:	<b>24/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>37390</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4223</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

Options	
Radio CD	Seats electric R
GPS storage	Seats electric F L
GPS storage	HD
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>











Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/50/17/89 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

Assistance equipment	
Runflat	<b>Yes</b>

Total cost ex VAT	<b>2627,92</b>
Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>308,20</b>



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	452,20
	
Door F L, Dent(s), Acceptable	0,00
No pictures to display	
Certificate Of Conformity, Missing, Acceptable	0,00
	
Door R L, Dent(s), PDR - Paintless dent repair	63,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	548,20
	
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
	
Rearlight L tailgate, Crack, E - Replace	176,29
	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	338,08

