



BMW 118 D: HZ5839

Vinnumber:	WBA1S51070V834714	Versionname:	2.0 118D (110KW)
First Registrationdate:	13/10/2016	Fiscalpower:	
Expertise Mileage:	56869	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/50/17/89 W LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	981,75
Door F L, Dent(s), PDR - Paintless dent repair	63,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	---------------



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 32,40



Certificate Of Conformity, Missing, P - Check 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Dent(s), Acceptable 0,00

No pictures to display