



## VOLKSWAGEN Golf: 1F5I370

Vinnumber:	<b>VWZZZAUZEW125256</b>	Versionname:	<b>GOLF BER Highline 105PK</b>
First Registrationdate:	<b>9/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>111371</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3310</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>
Adaptive cruise control	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	189,00
-------------------	--------

Sill outer R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Bonnet, Bad repair, Acceptable 0,00



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00

