



VOLKSWAGEN Polo: 1HSC104

Vinnnumber:	WVWZZZ6RZFY132099	Versionname:	POLO Comfortline BMT
First Registrationdate:	18/09/2014	Fiscalpower:	90PK
Expertise Mileage:	104261	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 25100	Parking lot:	3313
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2326,94
-------------------	---------

Door F R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Interior, Dirty, Cleaning	25,00
---------------------------	-------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Door R R, Scratch(es), Acceptable 0,00



Roof, Dent(s), LI - Repair and paint (complete) 385,20



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Wing R L, Dent(s), Acceptable 0,00



Bumper R, Dent(s), LI - Repair and paint (complete) 169,44



Rearview mirror housing L, Scratch(es), Acceptable 0,00

Bonnet, Dent(s), LI - Repair and paint (complete) 232,06

No pictures to display



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), Acceptable 0,00



Door F L, Rust, LI - Repair and paint (complete) 254,68



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Dent(s), PDR - Paintless dent repair 63,00



Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Engine protective plate, Broken, E - Replace 98,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

