


BMW 1 HATCH: GZ4365

Vinnumber:	WBA1V91080V739934	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	29/09/2016	Fiscalpower:	
Expertise Mileage:	60759	Power Kw:	85
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1116
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/89 W LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Total cost ex VAT	1158,20
Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Forfeit	25,00


Seat cover F R, Stain, Forfeit
25,00



Wing R L, Dent(s), PDR - Paintless dent repair	63,00
------------------------------------------------	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Certificate Of Conformity, Missing, Acceptable	0,00
------------------------------------------------	------



Bumper R, Hole, Le - Replace and paint	651,00
----------------------------------------	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Bumper grille F R, Broken, E - Replace	32,40
----------------------------------------	-------



Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

