



VOLVO V40 CROSS COUNTRY: 1RGC561

Vinnumber:	YV1MZ74L1H2127446	Versionname:	2.0 D2 KINETIC
First Registrationdate:	15/12/2016	Fiscalpower:	
Expertise Mileage:	45148	Power Kw:	88
Bodytype:		Body color:	Beige
Gearbox:	MAN 6 VIT	Body color:	BEIGE
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OK	Oil level:	OK
Maintenance:	12645 KM 1 MAAND	Parking lot:	1212
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	Tow bar removable
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
Adaptive cruise control	
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm


















Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1332,83
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------

			Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
			Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
			Sill outer R, Scratch(es), It - Spot repair	115,56
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
				
			Bumper trim R, Scratch(es), Smart repair	110,64
			Bumper F, Stone chip(s), Acceptable	0,00
