



**VOLKSWAGEN Passat: 1GIL218**

Vinnumber:	<b>WVWZZZ3CZEE099291</b>	Versionname:	<b>PASSAT VAR Comfortline</b>
First Registrationdate:	<b>17/02/2014</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>162137</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Beige</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4105</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Firestone: 5 mm</b>	Re.R.	<b>Firestone: 5 mm</b>

**Assistance equipment**


Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>446,80</b>
-------------------	---------------

Bonnet, Dent(s), Acceptable	<b>0,00</b>
-----------------------------	-------------

*No pictures to display*

Rear spoiler, Dent(s), PDR - Paintless dent repair	<b>63,00</b>
--	--------------



Rear window, Scratch(es), E - Replace	<b>0,00</b>
---------------------------------------	-------------



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 109,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

