



## VOLVO XC60: 1HTJ068

Vinnnumber:	<b>YV1DZ81A4F2674170</b>	Versionname:	<b>XC60 D4 4WD Kinetic</b>
First Registrationdate:	<b>29/09/2014</b>	Fiscalpower:	<b>181PK</b>
Expertise Mileage:	<b>109591</b>	Power Kw:	<b>133</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4214</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	<b>HD</b>	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>235/65/17/104 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>464,72</b>
Door R L, Dent(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door F L, Dent(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>254,16</b>



Bumper F R, Scratch(es), It - Spot repair	115,56
---	--------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

