



AUDI A1 SPORTBACK: 1PXN712

Vinnumber:	WAUZZZ8X9HB031652	Versionname:	1.4 TDI 66kW
First Registrationdate:	6/10/2016	Fiscalpower:	
Expertise Mileage:	39717	Power Kw:	66
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4523
Maintenance:	BINNEN 20900 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	546,12
-------------------	---------------

Bumper R, Scratch(es), It - Spot repair	115,56
---	---------------



SD card, Missing, E - Replace	220,00
-------------------------------	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F L, Scratch(es), It - Spot repair 115,56



Tailgate, Dent(s), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

