


**RENAULT Grand Scenic: 1GTK338**

Vinnnumber:	<b>VF1JZ14P650749646</b>	Versionname:	<b>Energy Life 7pl.110PK</b>
First Registrationdate:	<b>24/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>179123</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3426</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/96 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1418,69</b>
-------------------	----------------

Wing R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Sill outer L, Dent(s), PDR - Paintless dent repair	<b>63,00</b>
--	--------------











Rocker panel inner R L, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

*No pictures to display*

Door R R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Alloy rim F R, Scratch(es), 11 - Repair and paint (complete)	<b>95,00</b>
--	--------------

		
Door F L, Dent(s), PDR - Paintless dent repair		82,80
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)		163,56
		
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		302,16
		
Sill outer R, Dent(s), PDR - Paintless dent repair		82,80
		
Tailgate, Dent(s), PDR - Paintless dent repair		63,00
		
Rocker panel inner F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Maintenance, Maintenance, Acceptable		0,00
		
Wing F R, Scratch(es), LI - Repair and paint (complete)		288,21
		
Bumper F, Scratch(es), LI - Repair and paint (complete)		278,16

