



VOLKSWAGEN Golf: 1HLZ166

Vinnumber:	WVWZZZAUZFW019549	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	25/08/2014	Fiscalpower:	
Expertise Mileage:	107277	Power Kw:	77
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 10100 KM OF 25 DAGEN	Parking lot:	3622
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	628,72
--------------------------	---------------

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
--	---------------



Trunk lid covering R, Scratch(es), Smart repair	110,64
--	---------------



Bumper F, Scratch(es), Acceptable 0,00



Seat cover F L, Burned, Smart repair 64,32



Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Wing F R, Dent(s), Acceptable 0,00

