



VOLKSWAGEN Tiguan: QF8360

Vinnnumber:	WVGZZZ5NZFW507381	Versionname:	TIGUAN 4M Sport&Style BMT DSG 140PK Aut.
First Registrationdate:	2/07/2014	Fiscalpower:	
Expertise Mileage:	154116	Power Kw:	103
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3115
Maintenance:	BINNEN 7300 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/17/96 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 678,91

Door R R, Dent(s), Acceptable 0,00





Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00



Bumper F L, Scratch(es), Acceptable 0,00



Rocker panel inner R R, Scratch(es), Acceptable 0,00



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete) 115,56



Wing R R, Scratch(es), Acceptable 0,00



Door R L, Dent(s), LI - Repair and paint (complete) 318,35

