


RENAULT Kangoo Express: 1FJK600

Vinnnumber:	VF1FW58H549448089	Versionname:	KANGOO EXPR.MAXI Energy Gr.Conf.90PK
First Registrationdate:	16/07/2013	Fiscalpower:	
Expertise Mileage:	92314	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4709
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Windows electric F		Rear parking sensors	
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 T Steel			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	763,61
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Broken, E - Replace	22,50
--------------------------------------	-------



Bumper F, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Wing F L, Scratch(es), It - Spot repair	115,56
---	--------




Wheel cover F L, Broken, E - Replace 22,50




Wheel cover R R, Scratch(es), E - Replace 22,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bumper F, Scratch(es), Smart repair 110,64



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76

