



VOLKSWAGEN Caddy: 1DWS998			
Vinnnumber:	WV1ZZZ2KZDX021004	Versionname:	CADDY MAXI VAN B/F
First Registrationdate:	20/09/2012	Fiscalpower:	102PK
Expertise Mileage:	14190	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV18
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options		
Radio CD	Type of Tow bar	Tow bar removable
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/95 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	1530,47
Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,13



Bumper F, Dent(s), E - Replace	398,40
--------------------------------	--------





Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Sill outer L, Dent(s), LI - Repair and paint (complete) 232,88




Wing F R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door F L, Dent(s), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Supplementary brake lights, Broken, E - Replace

33,00

