



**VOLKSWAGEN Amarok: 1EZG363**

Vinnnumber:	<b>WV1ZZZ2HZDH015827</b>	Versionname:	<b>AMAROK 2C 4M Trendline</b>
First Registrationdate:	<b>26/04/2013</b>	Fiscalpower:	<b>140PK</b>
Expertise Mileage:	<b>145055</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>GEEN MELDING</b>		
Maintenance:	<b>OK</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>
	<b>No Tow bar</b>

**Limited Technical Inspection**

**Degree of wear**

	<b>245/70/16/111 S LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 7 mm</b>	Fr.R.	<b>Bridgestone: 7 mm</b>
	Re.L.	<b>Bridgestone: 8 mm</b>	Re.R.	<b>Bridgestone: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>758,99</b>
Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Bumper grille, Broken, E - Replace	34,08



Interior, Damaged, Acceptable	0,00
-------------------------------	------

*No pictures to display*

Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	------



Rearview mirror housing R, Scratch(es), 67 - Polish	55,19
---	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display