



BMW 1 HATCH: HZ5834			
Vinnumber:	WBA1S51040V834623	Versionname:	2.0 118D (110KW)
First Registrationdate:	29/09/2016	Fiscalpower:	
Expertise Mileage:	52894	Power Kw:	110
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1309
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
GPS storage HD	Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting Headlighting LED	
Type of GPS GPS big screen color	
Type of Lining Lining fabrics	
Type of climate control Autom climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear					
	205/50/17/89 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm	
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm	

Assistance equipment	
	Runflat Yes
Total cost ex VAT	385,44
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80





Centre console, Scratch(es), Smart repair	110,64
---	--------



Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Certificate Of Conformity, Missing, Acceptable	0,00
--	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Wing R L, Dent(s), PDR - Paintless dent repair	63,00
--	-------

