


BMW X3: 1FNT520

Vinnumber:	WBAWY110200C57166	Versionname:	X3 sDrive18 143PK
First Registrationdate:	2/09/2013	Fiscalpower:	
Expertise Mileage:	112692	Power Kw:	105
Bodytype:	SUV	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Luggage cover
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/99 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1762,24
Bonnet, Scratch(es), Acceptable	0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------






Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display