



FORD Grand C-Max: 1EBN768

Vinnnumber:	WF0HXXWPBHCL26981	Versionname:	GR.C-MAX Trend St/St
First Registrationdate:	11/10/2012	Fiscalpower:	95PK
Expertise Mileage:	158972	Power Kw:	70
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4407
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	SD	Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 4 mm
	Re.L.	Semperit: 4 mm	Re.R.	Semperit: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1472,83
Interior, Dirty, Cleaning	25,00




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Door R R, Scratch(es), 67 - Polish 0,00



Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 268,18



Door F L, Dent(s), Acceptable 0,00



Bumper spoiler F, Deformed / Strained, E - Replace 42,00

