



BMW 116 D: GZ4372			
Vinnnumber:	WBA1V91010V739385	Versionname:	1.5 D
First Registrationdate:	13/10/2016	Fiscalpower:	
Expertise Mileage:	40405	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1331
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/50/17/89 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Runflat	No
Total cost ex VAT	1525,40
Wing R R, Dent(s), LI - Repair and paint (complete)	356,20



Roof pillar R, Hail damage, PDR - Paintless dent repair	63,00
---	--------------



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Boot cover, Missing, E - Replace 50,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, P - Check 0,00

No pictures to display

Roof pillar L, Hail damage, PDR - Paintless dent repair 63,00



Bonnet, Hail damage, PDR - Paintless dent repair 201,60



Roof, Hail damage, PDR - Paintless dent repair 142,20



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 235,80




Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 235,80



Rocker panel inner R R, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 82,80



Sill trim L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

