



AUDI A1 SPORTBACK: 1PYB951

| | | | |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber: | WAUZZZ8X5HB031342 | Versionname: | 1.4 TDI 66kW |
| First Registrationdate: | 11/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 47836 | Power Kw: | 66 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4313 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|--------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | SD Rear parking sensors |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 185/60/15/84 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 169,44 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|---------------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 169,44 |
|---|---------------|





| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |