


BMW X3: 1FTJ666

Vinnnumber:	WBAWY110500C52740	Versionname:	X3 sDrive18 136PK Aut.
First Registrationdate:	18/10/2013	Fiscalpower:	
Expertise Mileage:	140561	Power Kw:	100
Bodytype:	SUV	Body color:	Beige
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3710
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/99 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Seat cover F L, Worn, Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), Acceptable			0,00

No pictures to display