



AUDI Q5: 1NKU766			
Vinnumber:	WAUZZZ8R3GA102897	Versionname:	2.0 TDI 100KW
First Registrationdate:	14/03/2016	Fiscalpower:	
Expertise Mileage:	186866	Power Kw:	100
Bodytype:		Body color:	Anthracite
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4816
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	235/60/17/102 H LightMetal			
	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			573,64
Sill trim R L, Scratch(es), Smart repair			110,64

			
Door panel R L, Scratch(es), Smart repair			110,64



Trunk lid covering R, Scratch(es), E - Replace 173,80



Door F R, Dent(s), PDR - Paintless dent repair 63,00



Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Hole, Le - Replace and paint 0,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display