


**LU Volkswagen Golf: SF8602**

Vinnnumber:	<b>WVWZZZAUZFW202628</b>	Versionname:	<b>2.0 TDI 135KW GTD BMT DSG</b>
First Registrationdate:	<b>22/04/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>34664</b>	Power Kw:	<b>135</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4722</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	
Sport seats		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/40/18/92 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

**Total cost ex VAT** 1992,38

**Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)** 95,00

**Door moulding Lower R R, Scratch(es), E - Replace** 114,00

		Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
		Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
		Tyre F L, Tear, E - Replace	132,00
		Bumper F R, Scratch(es), Smart repair	110,64
		Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
		Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
		Wing F R, Rust, LI - Repair and paint (complete)	220,18
		Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80



Alloy rim F R polished, Scratch(es), E - Replace 235,20

