



OPEL Astra: 1FJG065			
Vinnnumber:	W0LPC6DA7D1128326	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	101114	Power Kw:	70
Bodytype:		Body color	Brown
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3102
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/60/16/91 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1383,63
Door R R, Scratch(es), LI - Repair and paint (complete)			318,35



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)	358,50
---	---------------



Wing R L, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Roof, Scratch(es), Acceptable 0,00

No pictures to display