



## VOLKSWAGEN Sharan: 1GWT396

Vinnnumber:	<b>WVWZZZ7NZEV040828</b>	Versionname:	<b>SHARAN Comfortline BMT</b>
First Registrationdate:	<b>21/05/2014</b>	Fiscalpower:	<b>115PK</b>
Expertise Mileage:	<b>205322</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>4511</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/60/16/99 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

## Assistance equipment

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

Total cost ex VAT 2880,35

Dashboard, Glue residues, Cleaning 25,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Interior, Stain, Acceptable 0,00

No pictures to display

Door frame F R, Dent(s), It - Spot repair 115,56



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door frame R L, Dent(s), It - Spot repair 115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Headlight L, Scratch(es), E - Replace 396,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Roof pillar L, Scratch(es), It - Spot repair 115,56

