



HYUNDAI I40 WAGON: SF8151

Vinnnumber:	KMHLC81UAEU086912	Versionname:	1.7 CRDI 136HP GO!
First Registrationdate:	16/12/2014	Fiscalpower:	
Expertise Mileage:	275628	Power Kw:	100
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4222
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2746,83
-------------------	---------

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Roof, Rust, LI - Repair and paint (complete)	481,50
--	--------



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50



Luggage space cover, Missing, E - Replace 240,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Crack, Le - Replace and paint 1034,68

