



**VOLKSWAGEN TIGUAN: 1GWB111**

|                                   |                          |              |   |
|-----------------------------------|--------------------------|--------------|---|
| Vinnnumber:                       | <b>WVGZZZ5NZEW116446</b> | Versionname: | <b>TIGUAN Sport &amp; Style BM Tech.110PK</b> |
| First Registrationdate:           | <b>15/05/2014</b>        | Fiscalpower: |   |
| Expertise Mileage:                | <b>155448</b>            | Power Kw:    | <b>81</b>                                     |
| Bodytype:                         | <b>SUV</b>               | Body color   | <b>Brown</b>                                  |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                                |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                              |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                                     |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>2427</b>                                   |
| Battery functioning               | <b>Yes</b>               |              |   |
| Number of doors                   | <b>5</b>                 |              |   |
| Number of seats                   | <b>5</b>                 |              |   |
| Number head rests                 | <b>5</b>                 |              |   |
| Rims summer                       | <b>Aluminium</b>         |              |   |
| Category                          | <b>Passenger Car</b>     |              |   |
| Oil level                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |   |

**Options**

|                                |                             |                       |  |
|--------------------------------|-----------------------------|-----------------------|--|
| Radio CD                       |                             | Central consol F      |  |
| GPS storage                    |                             | Luggage cover         |  |
| GPS storage                    | <b>HD</b>                   | Front parking sensors |  |
| Windows electric F             |                             | Rear parking sensors  |  |
| Windows electric R             |                             |                       |  |
| Steering wheel multifunctional |                             |                       |  |
| Seats F heated                 |                             |                       |  |
| Type of headlighting           | <b>Headlighting Xenon</b>   |                       |  |
| Type of GPS                    | <b>GPS big screen color</b> |                       |  |
| Type of Lining                 | <b>Lining leather</b>       |                       |  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/60/17/96 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 2 mm</b> | Fr.R. | <b>Goodyear: 2 mm</b> |
|               | Re.L.                            | <b>Goodyear: 2 mm</b> | Re.R. | <b>Goodyear: 2 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>132,00</b> |
|-------------------|---------------|

|                                   |             |
|-----------------------------------|-------------|
| Bumper F, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|                               |             |
|-------------------------------|-------------|
| Door R R, Dent(s), Acceptable | <b>0,00</b> |
|-------------------------------|-------------|

*No pictures to display*

|                             |               |
|-----------------------------|---------------|
| Tyre F R, Flat, E - Replace | <b>132,00</b> |
|-----------------------------|---------------|



|                               |             |
|-------------------------------|-------------|
| Tailgate, Dent(s), Acceptable | <b>0,00</b> |
|-------------------------------|-------------|

*No pictures to display*