



AUDI A1 SPORTBACK: 1PYB719

Vinnumber:	WAUZZZ8X0HB032107	Versionname:	1.4 TDI 66kW
First Registrationdate:	11/10/2016	Fiscalpower:	
Expertise Mileage:	78797	Power Kw:	66
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	SD		
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/15/88 H LightMetal			
Summer tyres:	Fr.L. BF Goodrich: 5 mm	Fr.R. BF Goodrich: 5 mm	
	Re.L. Uniroyal: 6 mm	Re.R. Uniroyal: 6 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			489,60
Bumper F, Scratch(es), LI - Repair and paint (complete)			169,44



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Boot carpet, Stain, Cleaning 25,00



Bumper grille F L, Broken, E - Replace 30,72

