


**AUDI A3: XC8507**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>WAUZZZ8V1F1058877</b> | Versionname: | <b>A3 SEDAN clean diesel Ambition 184PK</b> |
| First Registrationdate:            | <b>20/10/2014</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>126560</b>            | Power Kw:    | <b>135</b>                                  |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                              |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                   |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2532</b>                                 |
| Battery functioning:               | <b>Yes</b>               |              |   |
| Number of doors:                   | <b>4</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| Radio CD                       |                              | Central consol F     |
| GPS storage                    | <b>SD</b>                    | Rear parking sensors |
| GPS storage                    |                              |                      |
| Windows electric F             |                              |                      |
| Windows electric R             |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Seats F heated                 |                              |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining leather</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |
| Sport seats                    |                              |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/40/18/92 Y LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Continental: 3 mm</b> | Fr.R. | <b>Continental: 3 mm</b> |
|                                  | Re.L. | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|   |                |
|---|----------------|
| Total cost ex VAT   | <b>1568,82</b> |
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b>   |



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Backrest cover F L, Damaged, Acceptable

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Tailgate, Chemical polution, LI - Repair and paint (complete)

301,68



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer L, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00

