


AUDI A1 SPORTBACK: 1PYB621

| | | | |
|------------------------------------|-------------------------|--------------|---------------------|
| Vinnumber: | WAUZZ8XXHB031014 | Versionname: | 1.4 TDI 66kW |
| First Registrationdate: | 11/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 54657 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Dark Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3612 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Luggage cover |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 185/60/15/84 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 2 mm | Fr.R. | Michelin: 2 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|---|--------|
| Total cost ex VAT | 246,56 |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Scratch(es), LI - Repair and paint (complete) | 246,56 |

