



BMW 116D HATCH: GZ4387

Vinnumber:	WBA1V91080V739903	Versionname:	1.5 EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	26/10/2016	Fiscalpower:	
Expertise Mileage:	28984	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1409
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/50/17/89 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1845,21
-------------------	----------------

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Certificate Of Conformity, Missing, Acceptable 0,00



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 82,80



Outer door handle F L, Scratch(es), LI - Repair and paint (complete) 115,56



Sill outer R, Scratch(es), It - Spot repair 115,56



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), It - Spot repair 115,56



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00





Roof pillar R, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper moulding F L, Scratch(es), E - Replace

14,40

