



BMW 3: 1GAU476			
Vinnumber:	WBA3K91060F933230	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	10/12/2013	Fiscalpower:	
Expertise Mileage:	179411	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3813
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 1,8 mm	Fr.R.	Goodyear: 1,8 mm
	Re.L.	Goodyear: 1,8 mm	Re.R.	Goodyear: 1,8 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT		0,00
-------------------	--	------

Windscreen, Repaired, Acceptable		0,00
----------------------------------	--	------

No pictures to display

Bumper F, Scratch(es), Acceptable		0,00
-----------------------------------	--	------

No pictures to display

Door R L, Dent(s), Acceptable		0,00
-------------------------------	--	------

No pictures to display

No pictures to display

Roof, Chemical polution, Acceptable	0,00
-------------------------------------	------

No pictures to display

Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Seat cover F L, Tear, Acceptable	0,00
----------------------------------	------

