



BMW 3: 1GVP772

| | | | |
|-----------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | WBA3D91090J414275 | Versionname: | 3 BER 316d 116PK |
| First Registrationdate: | 13/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 166152 | Power Kw: | 85 |
| Bodytype: | | Body color: | Red |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance | 1/05/2018 | Parking lot: | 3633 |
| Maintenance | NOT OK | | |
| Battery functioning | Yes | | |
| Number of doors | 4 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| GPS storage | HD |
| GPS storage | |
| Windows electric F | |
| Windows electric R | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/60/16/92 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
| | Re.L. | BF Goodrich: 5 mm | Re.R. | BF Goodrich: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 550,20 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Maintenance, Maintenance, Execute | 0,00 |
|-----------------------------------|-------------|



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 487,20



Door F L, Dent(s), PDR - Paintless dent repair 63,00

