



BMW 3: 1HNV677

Vinnumber:	WBA3D91050KL54120	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	95015	Power Kw:	85
Bodytype:	Berline	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3116
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Windows electric R	
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Total cost ex VAT	619,48
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Door panel R R, Tear, Smart repair	110,64
------------------------------------	--------



Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), E - Replace	30,00



Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00



Door panel F R, Tear, Smart repair	110,64
------------------------------------	--------



Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	30,00

