


FORD Fiesta: 1FJQ716

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnumber: | WF0DXXGAKDDA09178 | Versionname: | FIESTA BER Trend ECONetic S/S 95PK |
| First Registrationdate: | 18/07/2013 | Fiscalpower: | |
| Expertise Mileage: | 138142 | Power Kw: | 70 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3209 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|-------------------------------|------------------|
| Radio CD | | Central consol F |
| GPS storage | | Luggage cover |
| GPS storage | HD | |
| Windows electric F | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| 175/65/15/91 H Steel | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 6 mm | Fr.R. | Uniroyal: 6 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|--|-------|
| Total cost ex VAT | 96,00 |
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |

No pictures to display

| | |
|-----------------------------------|-------|
| Door panel F R, Worn, E - Replace | 96,00 |
|-----------------------------------|-------|



| | |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|------|
| Bodywork, Not original part, Acceptable | 0,00 |
|---|------|

