



BMW X5: 1TTR312

Vinnumber:	WBAKT010500W18782	Versionname:	
First Registrationdate:	25/08/2017	Fiscalpower:	
Expertise Mileage:	20279	Power Kw:	180
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	3227
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
TV/DVD screen R		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			
Adaptive cruise control			
Sport seats			

Limited Technical Inspection







Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	275/40/20/106 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Bumper R, Dent(s), Le - Replace and paint	766,80
	
Rearview mirror R complete, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), E - Replace	277,44
	
Alloy rim R R polished, Scratch(es), E - Replace	277,44
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L polished, Scratch(es), E - Replace	277,44
	
Alloy rim R L polished, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Missing, E - Replace	54,60
	
Floor covering F R, Burned, Smart repair	64,32
	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Glove compartment lid, Broken, E - Replace	336,00



Charging cable (normal), Missing, E - Replace

350,00

