



CITROËN C4 Picasso: 1HJJ481

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | VF73A9HC8EJ748452 | Versionname: | DIESEL |
| First Registrationdate: | 1/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 68133 | Power Kw: | 85 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3806 |
| Maintenance: | 21100KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar removable |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/60/16/92 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|------------------------------------|---------------|
| Total cost ex VAT | 576,28 |
| Door R R, Scratch(es), 67 - Polish | 0,00 |



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00




Rearview mirror housing R, Scratch(es), Acceptable

0,00



Interior, Dirty, Cleaning

150,00



Door panel R L, Scratch(es), Smart repair

110,64



Wing R R, Scratch(es), 67 - Polish

0,00



Door R L, Scratch(es), Acceptable

0,00



Wheel bolt cover R L, Missing, E - Replace

15,00



| | |
|--|-------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|



| | |
|------------------------------------|------|
| Door F L, Scratch(es), 67 - Polish | 0,00 |
|------------------------------------|------|



| | |
|---|--------|
| Door panel R R, Scratch(es), Smart repair | 110,64 |
|---|--------|



| | |
|------------------------------------|------|
| Door F R, Scratch(es), 67 - Polish | 0,00 |
|------------------------------------|------|



| | |
|------------------------------------|------|
| Tailgate, Scratch(es), 67 - Polish | 0,00 |
|------------------------------------|------|

